

## Prairie View Lead Test Results

Date of sample	Time	Location	Tested by	Testing Method	Results
06/22/2017	10:12 PM	Kitchen PVS1 -1	Suburban Labs, Inc.	EPA 200.8	8.71
06/22/2017	10:12 PM	Kitchen PVS1 -2	Suburban Labs, Inc.	EPA 200.8	2.27
06/22/2017	10:14 PM	Kitchen PVS2 -1	Suburban Labs, Inc.	EPA 200.8	7.39
06/22/2017	10:14 PM	Kitchen PVS2 -2	Suburban Labs, Inc.	EPA 200.8	2.41
06/22/2017	10:04 PM	Hall PVF2-1	Suburban Labs, Inc.	EPA 200.8	7.03
06/22/2017	10:04 PM	Hall PVF2-2	Suburban Labs, Inc.	EPA 200.8	3.21
06/22/2017	10:10 PM	Hall PVF5-1	Suburban Labs, Inc.	EPA 200.8	4.7
06/22/2017	10:10 PM	Hall PVF5-2	Suburban Labs, Inc.	EPA 200.8	3.04

## Prairie View Lead Retest

Faucets and Fountain were replaced

08/03/2017	05:30 AM	Kitchen PVS1 #1	Suburban Labs, Inc.	EPA 200.8	0
08/03/2017	05:30 AM	Kitchen PVS1 #2	Suburban Labs, Inc.	EPA 200.8	0
08/03/2017	05:35 AM	Kitchen PVS2 #1	Suburban Labs, Inc.	EPA 200.8	0
08/03/2017	05:35 AM	Kitchen PVS2 #2	Suburban Labs, Inc.	EPA 200.8	0
08/03/2017	05:40 AM	Hallway PVF2 #1	Suburban Labs, Inc.	EPA 200.8	0
08/03/2017	05:40 AM	Hallway PVF2 #2	Suburban Labs, Inc.	EPA 200.8	0